**To:** Urdiales, Aaron[Urdiales.Aaron@epa.gov]

From: Land, Kelcey

Sent: Fri 8/7/2015 12:44:50 PM Subject: Fwd: Gold king mine - 4 final

ATT00001.htm

Sent from Kelcey Land's iPhone - tiny keyboard - please excuse typos!

Begin forwarded message:

From: "Sandoval, Joni" < Sandoval.Joni@epa.gov>

To: "Ostrander, David" < Ostrander. David@epa.gov>, "Land, Kelcey"

<<u>Land.Kelcey@epa.gov</u>>

Subject: Fwd: Gold king mine - 4 final

Sent from my iPhone

Begin forwarded message:

From: "Marilyn Smith" < m.smith@erllc.com < mailto:m.smith@erllc.com >>>

To: "Sandoval, Joni" < Sandoval.Joni@epa.gov < mailto: Sandoval.Joni@epa.gov >>, "Braun,

Richard" < Braun.Richard@epa.gov < mailto: Braun.Richard@epa.gov >>>

Subject: FW: Gold king mine - 4 final

The attached report was from when DRMS closed it . ER's task was to reopen it, and because ER knew it was something to be figured out as we went, ER placed a RFQ that selected a subcontractor for time and materials work. The subcontractor approach was the result of a meeting this winter at the subcontractor's office attended by the OSC, DRMS and the ER RM.

However the subcontractor selected was not scheduled to start until access to the mine was open. The sub was tentatively scheduled for 8/14.

From: Way, Steven [mailto:way.steven@epa.gov]

Sent: Thursday, September 11, 2014 10:36 PM

To: Matt Francis

<m.francis@erllc.com<mailto:m.francis@erllc.com><mailto:m.francis@erllc.com>>;

 $\underline{Allen.Sorenson@state.co.us} < \underline{mailto:Allen.Sorenson@state.co.us} > \underline{mailto:Allen.Sorenson$ 

Cc:

 $\underline{\textit{Jeff.Bryniarski@westonsolutions.com}} < \underline{\textit{mailto:Jeff.Bryniarski@westonsolutions.com}} > \underline{\textit{mailto:$ 

Subject: Gold king mine - DRMS adit closure

Matt, Jeff and Allen,

The attached report explains / shows the DRMS closure project. It provides a little perspective on the elevations and the piping, but it does not reveal the conditions that we are seeing.

The stinger pipe would suggest that the block was penetrated to relieve pressure and get drainage into the PVC (24") pipe.

If other ideas come to mind – let me know. Steve

Steven Way Federal On-Scene Coordinator Emergency Response Unit US EPA - Region 8 1595 Wynkoop Street Denver, CO 80202

Office: 303-312-6723

Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. Although this email has been scanned for malware, the sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you.